


FREESTANDING OFFICE SCREEN

Linking Screens
Inline Configuration

STEPS:

1. Carefully unwrap screens and position first screen where required.
Remove top cap to reveal inline link.
2. Slide inline link out of the sides you wish to link.
3. To form an inline link, align next screen as shown in image.
4. Slide inline link in-between the side trims as shown to join the screens.
5. Ensure the link is flush with the side trims and then replace the top caps.



01733 511030
sales@xldisplays.co.uk